


WO 00/41754

1 / 33


PCT/EP00/00194



WO 00/41754

2 / 33

PCT/EP00/00194



WO 00/41754

3 / 33

PCT/EP00/00194




Fig. 3

WO 00/41754

4 / 33

PCT/EP00/00194




Fig. 4

WO 00/41754

5 / 33

PCT/EP00/00194




Fig. 5

WO 00/41754

6 / 33

PCT/EP00/00194





Fig. 6

WO 00/41754

7 / 33

PCT/EP00/00194



WO 00/41754

8 / 33

PCT/EP00/00194





Fig. 9

WO 00/41754

9 / 33

PCT/EP00/00194



WO 00/41754

10 / 33

PCT/EP00/00194




Fig. 11




Fig. 12

WO 00/41754

11 / 33

PCT/EP00/00194





Fig. 13

WO 00/41754

12 / 33

PCT/EP00/00194



WO 00/41754

13 / 33

PCT/EP00/00194




Fig. 15

WO 00/41754

14 / 33

PCT/EP00/00194




Fig. 16

WO 00/41754

15 / 33

PCT/EP00/00194





Fig. 17

WO 00/41754

16 / 33

PCT/EP00/00194



WO 00/41754

17 / 33

PCT/EP00/00194




Fig. 19

WO 00/41754

18 / 33

PCT/EP00/00194




Fig. 20




Fig. 21

WO 00/41754

19 / 33

PCT/EP00/00194




Fig. 22

WO 00/41754

20 / 33

PCT/EP00/00194




Fig. 23

WO 00/41754

21 / 33

PCT/EP00/00194




Fig. 24

WO 00/41754

22 / 33

PCT/EP00/00194




Fig. 25

WO 00/41754

23 / 33

PCT/EP00/00194





Fig. 26

WO 00/41754

24 / 33



PCT/EP00/00194



WO 00/41754

25 / 33


PCT/EP00/00194

*Fig. 28**Fig. 29*

WO 00/41754

26 / 33

PCT/EP00/00194



WO 00/41754

27 / 33

PCT/EP00/00194




Fig. 31

WO 00/41754

28 / 33

PCT/EP00/00194




Fig. 32

WO 00/41754

29 / 33

PCT/EP00/00194




Fig. 33

WO 00/41754

30 / 33

PCT/EP00/00194




Fig. 34





Fig. 35

WO 00/41754

31 / 33

PCT/EP00/00194

*Fig. 36*

WO 00/41754

32 / 33

PCT/EP00/00194




Fig. 37

WO 00/41754

33 / 33

PCT/EP00/00194




Fig. 40




Fig. 39




Fig. 38

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ **BLACK BORDERS**
- ☐ **IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- ☐ **FADED TEXT OR DRAWING**
- ☐ **BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- ☐ **SKEWED/SLANTED IMAGES**
- ☐ **COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- ☐ **GRAY SCALE DOCUMENTS**
- ☐ **LINES OR MARKS ON ORIGINAL DOCUMENT**
- ☐ **REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- ☐ **OTHER:** _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.